Waters™

アプリケーションノート

Monitoring System Performance With System Suitability and Control Charts in Empower

Haining Pee

Waters Corporation

Abstract

System Suitability is a series of injections you can make to help you determine the suitability and effectiveness of your chromatographic system before use. System Suitability requirements must pass to guarantee the quality of the sample run results. System Suitability injections also enable you to monitor method performance over time.

Introduction

Empower™ Chromatographic Data System (CDS) can assess System Suitability standards interactively, checking the performance of standards against your System Suitability requirements in an automated, unattended manner. Upon failing the requirements, Empower CDS can be configured to continue the sample run, abort the sample run, or reinject the standards. Subsequently, System Suitability parameters can be plotted on control charts for data trending. Data trending allows users to monitor method performance and take corrective action before out-of-specification products are produced.

The functionality of interactive System Suitability and control charts are highlighted through this case study below:

Six System Suitability standards are analyzed at the start of the sample run and, to ensure that the system is performing well, the analyte's Retention Time must fall within $\pm 3\%$ of the target Retention Time.

Analyte	Target retention time (min)
Acesulfame K	0.650
Benzoic acid	1.004
Sorbic acid	1.450
Caffeine	1.700
Aspartame	2.000

Table 1. Table of target Retention Time of the various analytes.

Results and Discussion

In the Processing Method

First, System Suitability criteria are set up in your Empower Processing Method through the *Limits Tab*. Click on the target component and select the parameters that you wish to monitor in the Suitability Limits table. For this example, the target Retention Time and an error % of 3% for all components has been set.

(>	1	₹ Flag Valu	es Outside L	imits															
								Cuit-l	oility Comp	nonto									
													_			FI 0			
	Name					Calculate Suit Results					Flag Outside Limits								
	Acesulfame K					V						▼.							
2	Benzoic Acid					⊽						V							
	Sorbic Acid					⋉					. □								
	Caffeine	Caffeine							<u></u>				V						
;	Aspartame					V													
#																			
_						_		_	itability Lin	_									
1	Field Name	Target	Error %	Lower E	rror Limit (LCL)) Upper	Upper Error Limit (UCL)		Warning 9	6 Low	er Wa	arning Limit	Upper	Upper Warning Limit		Ignore Blan	200000000000000000000000000000000000000	Check Limits	
	Retention Time	0.650	3.00		0.631	1		0.670										During Qua	intitation
ene	gyalan (Smootlingschild) Cunganiens (in	nguilfy Fean Hallon	as envano (cura	demonstrate (s	arred Groups Timed Groups	Suranny Lawre)	Noise and Drift		4 F Jud			omponents[inourts]Pe	pi Rofico Júd ice l	n Radios Calcult Lev	ours Ours Jr.	arret Groups Timed Co	cospo Curiochily Canto	binso and Data	
ense;	P regvisier Grade Levis	nguitty Pain Hallon (Suitability Compon	ents	Drastal Casas (W b los			ongonada] Impudy] Py David Link	gi Rufico SiG loe l	Date	bliky Compon	ents	cospo (Suiscolle) Lianda		
	IF negvales Grade Leve Same	ngutty Pean Maton s		Suitability Comoon Calculate Suit Fiero	ents	(many cases)	Flag Outside Limi	ite	3			- Dutido (indo	in Radico Juli Inn I	Date	bliky Compon late Suit Ress	ents	rospo Dulocity Limbs	Flag Outside Lin	nia .
Ne.	P regvisier Grade Levis	ngutty Pass Mators		Suitability Compon	ents	busing twee		its	1 Au		Register	- Dutido (indo	ar Rafes (MS los I	Date	bliky Compon	ents	cospo (Salacido) Unida		nis .
to to	P hay/see-Outer Leve Same routime K totsAdd totAdd	ngum Pass Hatos o		Suitability Compon Catodine Suit Fersi IP IP	ents	(man) (man)	Flag Cutside Limi	its	1 Air 2 fan 3 80	offerre K roic Acid	Register	- Dutido (indo	a Rates Sel ton 1	Date	bility Compon late Suit Reso IV	ents	cospo (Balgosite, Uarda	Flag Outside Lin	els :
Are Set Café	P register Circle Lane Same routisms K spec M44 3c Acid bore	nguith [Pean Haton s		Suitability Compon Calculate Suit Fless P	ents	STOREGIST CHARLE (Flag Cutside Limi	its	1 Air 2 Sen 3 Sel 4 Cub	(Final Notice Notice Acid	Register	- Dutido (indo	o Rafes 345 les l	Date	bility Compon late Suit Perso IV	ents	case Salesile, Units	Flag Outside Lin	als -
Are Set Café	P hay/see-Outer Leve Same routime K totsAdd totAdd	ngwith[] Pean Maton s		Suitability Comoon Calculate Suit Flans P P P P	ents its	Division of many (Flag Cubide Limi	its	1 Air 2 Sen 3 Sel 4 Cub	offerre K roic Acid	Register	- Dutido (indo	as Bades (Art ton)	Solution Cubrical	bility Compon late Stat Ress IV IV IV	erds ults	page (Salacide, David	Flag Outside Lin SF SF SF SF	als :
Are Soit Cafe Aug	P Register-Oakli Line Stance S	er Ensrium &GL)	Upper Error Limit (u	Suitability Comoon Calculate Suit Ress P P P P Suitability Limit UCL) Maning %	ents its		Fing Custide Limit D D D D D D D D D D D D D	Oleda U	1 Acr 2 fee 3 500 4 Cah 6 Asp	State K roc Add SAM share	Flan	e Deside Links	est (LCL) Upper	Setal Calcul Setal Calcul Set Ever Limit (UCL)	bility Compon late Stat Ress IV IV IV	enta dis		Flag Outside Lim Flag	Check Lin
Are Soit Cafe Aug	P RegVales Oxfolic Lave Stance Involume K use, Ault Siz-Ault Involume Siz-Ault Siz-A		Upper Error Limit (u	Suitability Comoon Calculate Suit Ress P P P P	erets this		Flag Cuside Limi	lyfer	1 Acr 2 fee 3 500 4 Cah 6 Asp	District K rosc Acid BASH Plane	F Regvise	- Durida Lines		Date Culcul	bility Compon late Stat Ress IV IV IV	enta dis		Flag Outside Lin SF SF SF SF SF	Seatt on the
Are Soit Cafe Aug	P Register-Oakli Line Stance S	er Ensrium &GL)	Upper Error Limit (u	Suitability Comoon Calculate Suit Ress P P P P Suitability Limit UCL) Maning %	erets this		Fing Custide Limit D D D D D D D D D D D D D	Oleda U	1 Acr 2 fee 3 500 4 Cah 6 Asp	State K roc Add SAM share	Flan	e Deside Links	est (LCL) Upper	Setal Calcul Setal Calcul Set Ever Limit (UCL)	bility Compon late Stat Ress IV IV IV	enta dis		Flag Outside Lim Flag	Check Lini
Acer Sort Caffi August	P Register-Oakli Line Stance S	er Ensy Limit (LCL) 9,574	Upper Error Limit (s)	Suitability Compon Calculate Suit First P P P P Suitability Limit UCL) Warning %	ords its	per Warring Limit.	Flag Outside Limi	Oleda U	2 fan 2 fan 3 500 6 fan	guitarre K roc Add oc Add oc Add oc Add oc Add oc Add oc Add oc Add oc Add oc Add	Ran Target 1 430	e Deside Links	not (LCX.) Upper	Solid Calcul Grant Solid on Ener Lind (VCL) 1 43N	bility Componing Comp	enda dra I Linear Warning Linea	Lipper Warning Limit	Flag Outside Lim SP	Check Lin
Are Solt Caff Asp	F Pagnise Coloris Lines States States States States States States States Test States	er Ensy Limit (LCL) 9,574	Upper Error Limit (s)	Subshity Componed Calculate State Field Fi	ares toward times through	per Warring Limit.	Flag Outside Limi	Oleda U	2 fan 2 fan 3 500 6 fan	Suffere K roc Acid Substitute Fulld Name Internal	Target 1 450	P. Deside Links # Error % Linear Error Li 2 80	not (LCX.) Upper	Durint Colored Colored Direct Limit (NCL) 1 42N Rabox [Consustance	bolis Componists Soil Reservery Soil Soil Soil Soil Soil Soil Soil Soil	ents As Lover Warning Link Lover Warning Link amed Scoops [treed Sc	Lipper Warning Limit	Flag Outside Lim SP	Check Lin
Sort Caffe	P Pagniser Coloris Lines Salens Solidate Solidate Solidate Solidate Fatilitates Target Eron N Love antene 1.004 330 paten Smith application Smith applic	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Suitability Compon Calculate Suit First P P P P Suitability Limit UCL) Warning %	ords in a Supering Line Sport Server	per Warring Limit.	Flag Outside Limi	Check U During Quarti	2 fan 2 fan 3 500 6 fan	Suffere K roc Acid Substitute Fulld Name Internal	Target 1 450	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Suisi Colorio Colorio Governmento John Table 1454 Governmento John Colorio Governmento John Colo	bility Componing Comp	onto the following Line of the Ground Travel Ground Travel Ground Travel Grown onto Grown	Lipper Warning Limit	Flag Outside Lim SP	Check Lin During Quantita
in the second	P Pignae Color Leve Signa Fall Name Stock Mill Sto	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Subshity Coroon Calculate Sal Fees P P P Subshity Unit LCQ Weining % 3054 Subshity Corpor Calculate Sal Res Subshity Corpor Calculate Sal Res Subshity Corpor Calculate Sal Res	ords in a Supering Line Sport Server	per Warring Limit.	Flag Cuside Limit Flag State State Space State Values Flag Occade Limit Plag Occade Limit	Check U During Quarti		Support Name And Water And Water And Mane	Ray Name Targer 1 400 Play Name C Pl	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Suisi Colorio Colorio Governmento John Table 1454 Governmento John Colorio Governmento John Colo	bility Componing Comp	onto the following Line of the Ground Travel Ground Travel Ground Travel Grown onto Grown	Lipper Warning Limit	Flag Outside Lin P P P P P P P P P P P P P	Check Lin During Quantita
Series Se	P Projected Criminal Lance Statement Comment	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Suitability Compon Calculate Suit Fern P P P Suitability Limit CCO Winning St 2021 Winning St 2021 Winning St 2021 State Compon Calculate Suit Resp P	ords in a Supering Line Sport Server	per Warring Limit.	Flag Cutoide Limit Si Si Si Si Si Si Si Si Si	Check U During Quarti		Auffaire K rock Acid whole whose read Name read Tone powderse K rock Acid volume solum Tone powderse K rock Acid	Ray Name Targer 1 400 Play Name C Pl	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Suisi Colorio Colorio Governmento John Table 1454 Governmento John Colorio Governmento John Colo	bility Compounds Dail Research Street South Research Warning No. Southarthorny (in the South Research Street South Research Street South Research Street South Research	onto the following Line of the Ground Travel Ground Travel Ground Travel Grown onto Grown	Lipper Warning Limit	Flag Outside Line P P P P P P P P P P P P P	Check Lin During Quantita
See	P Paymen Order Leve Signe Fall Name Stock Mill Sto	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Suitability Componing State St	ords in a Supering Line Sport Server	per Warring Limit.	Flag Cutable Limit D D D D D D D D D D D D D	Check U During Quarti		Support Name Field Name Fiel	Ray Name Targer 1 400 Play Name C Pl	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Suisi Colorio Colorio Governmento John Table 1454 Governmento John Colorio Governmento John Colo	bility Componing Comp	onto the following Line of the Ground Travel Ground Travel Ground Travel Grown onto Grown	Lipper Warning Limit	Flag Outside Lin P P P P P P P P P P P P P	Check Lin During Quantita
Series Series Series Series Series	P Projected Criminal Lance Statement Comment	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Suitability Compon Calculate Suit Fern P P P Suitability Limit CCO Winning St 2021 Winning St 2021 Winning St 2021 State Compon Calculate Suit Resp P	ords in a Supering Line Sport Server	per Warring Limit.	Flag Cutoide Limit Si Si Si Si Si Si Si Si Si	Check U During Quarti		Subtrace N moc Acid moc Acid moc Acid mise shame fulld Name scient Time purchase Time purchase X moc Acid a Acid moc Acid a Acid moc Acid	Ray Name Targer 1 400 Play Name C Pl	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Suisi Colorio Colorio Governmento John Table 1454 Governmento John Colorio Governmento John Colo	bolity Composite State Results Fig. Fig.	onto the following Line of the Ground Travel Ground Travel Ground Travel Grown onto Grown	Lipper Warning Limit	Flag Outside Lin Si Si Si Si Si Si Si Si Si	Check Lin During Quantita
Acer Sets Sets Sets Sets Sets	P Projected Criminal Lance Stateman Stateman Stateman Stateman Stateman Frest Stateman	er Ensy Limit (LCL) 9,574	Upper Ener Limit (s) 1 MOtes Fartes() Curte	Subshilly Coroon Calculate Sur Res. P P P P Subshilly Limit LOS Memory Is Subshilly Limit Subshilly Compac Calculate Sub Res. P P P P P P P P P P P P	oreh D Lune Wiening zinn Lune Wiening zinn Lune Wiening zinn Lune Wiening zinn Lune Lune Wiening zinn Lune Lune Wiening zinn Lune Lune Wiening zinn Lune	per Warring Limit.	Flag Cutable Limit Page Cutable Limit Page Page Cutable Limit P	Check U During Quarti		Subtrace N moc Acid moc Acid moc Acid mise shame fulld Name scient Time purchase Time purchase X moc Acid a Acid moc Acid a Acid moc Acid	Ray Name Targer 1 400 Play Name C Pl	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	not (LCX.) Upper	Delail Calcul Calcul Calcul Go Error Linel (3-CQ) 1 4-04 Patical Calcul Calcul Calcul	bolity Components State Research State State Research Wildering St. Wildering St. Solity Components State Research St. St. St. St. St. St. St. St	erdo de la	Lipper Warning Limit	Flag Outside Line Flag Outside Line Flag Outside United Flag Outside Line	Check Lin During Quantita
Acer Best Acer Best Sent	P Projected classic Lance Stateme Stateme Stateme Stateme Stateme Tender Stateme Tender Stateme Tender Stateme Tender Stateme Tender Stateme Tender Stateme Statem	er Environ & Co.) C 074	Upper Ener Lines () 1 1 HOten Fathers [] Outlie	Suitability Componing State St	oreh D Lune Wiening zinn Lune Wiening zinn Lune Wiening zinn Lune Wiening zinn Lune Lune Wiening zinn Lune Lune Wiening zinn Lune Lune Wiening zinn Lune	per trianing Lines.	Fing Qualifie Limit D D D D Grant Direct Visions Fing Quarter Limit Fing Quarter Limit D D D Fing Quarter Limit D D D D D D D D D D D D D	Check U		Substitute K mod And water water food Name strian True relate strianter political And political food And political food political	Ram Target 1 + 420 1 + 420 Nam	Ener % Laver Ener Li 2 80 Onconents Innount (Fer	nel (LCL) Upper 1 4827	Dated Celevil Celevil 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0	bolis Composite Shift Research Shift Composite Shift Composite Shift Research Shi	undo also Vanning Line Lover Waning Line Lover Waning Line and Love Line Line and Li	Egger Warring Lind	Flag Outside Line Flag Outside Line Flag Outside United States And Line Flag Outside L	Check Limit Curey Quantital

Figure 1. Click on each of the target component and select the parameters you wish to monitor in the Suitability Limits table.

In the Method Set

The Processing Method is added into the Method Set to allow Empower to process and evaluate your System Suitability criteria during the run.




Figure 2. Adding the Processing Method to the Method Set to allow for automated processing.

In the Run Samples Window

After your Sample Set is set up, the Run Mode and Suitability Mode are configured to enable interactive System Suitability. In the *Run Mode*, choose "Run Only", "Run and Process", or "Run and Report" for online data processing. "Run and Process" and "Run and Report" will result in the generation of results. Here, select "Run and Process".




Figure 3. Select the Run Mode for online data processing.

The *Suitability Mode* allows you to configure Empower to take actions to continue the run, stop the run or reinject samples, in the event of System Suitability faults. Faults happen when the injection fails to meet the limits set. For this example, we will choose "Stop on Fault".

Z		3	13	ŀ		⊘ jjj _{H-ć-} Ru	n and Process	- 1	Continue on Fault	_
						Sample Set Method: Soft Drin	nk Analysis		Stop on Fault	
Ē	Vial	Inj Vol (uL)	# of Injs	Label	SampleName	Function	Method Set / Report or Export Method	Re N	Reinject on Fault Next Sample on Fault Next Sample Set on Fa	ault)
1	1	5.0	1		Blank	Inject Samples	Soft Drink Analysis ACQ		Ignore Faults	3.00
2	2	5.0	6	SST	System Suitability Standard	Inject Samples	Soft Drink Analysis ACQ		Normal	3.00
3						Summarize Custom Fields			Normal	
4	3	5.0	1		Standard 1	Inject Standards	Soft Drink Analysis ACQ		Normal	3.00
5	4	5.0	1		Standard 2	Inject Standards	Soft Drink Analysis ACQ		Normal	3.00
6	5	5.0	1		Standard 3	Inject Standards	Soft Drink Analysis ACQ		Normal	3.00
7	6	5.0	1		Standard 4	Inject Standards	Soft Drink Analysis ACQ		Normal	3.00
8	7	5.0	1		Standard 5	Inject Standards	Soft Drink Analysis ACQ		Normal	3.00
9	8	5.0	1		Sample A	Inject Samples	Soft Drink Analysis ACQ		Ignore Faults	3.00
10	9	5.0	1		Sample B	Inject Samples	Soft Drink Analysis ACQ		Ignore Faults	3.00
11	10	5.0	1		Sample C	Inject Samples	Soft Drink Analysis ACQ		Ignore Faults	3.00

Figure 4. Select the Suitability Mode to configure Empower to take specific actions in the event of a System Suitability failure.

Next, the System Suitability standards are analyzed. Empower continues your sample run if System Suitability limits pass or aborts the run if System Suitability limits fail.




Figure 5. Empower continues the sample run if System Suitability limits pass or aborts the run if System

Suitability limits fail. This allows for an unattended, hands-free operation.

Upon detecting a System Suitability fault in the second injection of the System Suitability standard, Empower aborts the run and indicates a suitability failure. You can review possible faults in the Review window.




Figure 6. Review window displaying System Suitability failure for Benzoic Acid.

System Suitability faults are automatically highlighted in red, bold, and italics for you. Here, it is observed that Benzoic Acid's Retention Time of 0.973 min falls outside the $\pm 3\%$ error range of 0.974 to 1.034 min.

Data Trending in Publisher

Benzoic acid's Retention Time can be trended across multiple injections to determine if there is a drift towards an out-ofspecification result. To observe the data trending across multiple results, a Summary Report is required. This can be set up through Method Properties. Access Method Properties through the Edit Menu and select Method Properties. Here, we choose a Summary by All report.




Figure 7. Method Properties in Report Publisher.




Figure 8. Report Publisher allows users to plot control charts via System Suitability groups.

On the right is the report method layout, while the list of report groups can be found on the left. System Suitability groups allow you to plot control charts. To observe the data trending for Retention Time, the SS Summary Plots are used. There are three display options for your Summary Plot, namely, Bar Plot, Line Plot, and Scatter Plot.

By default, Area will be trended for your Summary Plot. This can be changed in the Summary Plot Properties. Right click on the plot to access the Summary Plot Properties. There is an extensive selection of parameters – Empower built-in fields and custom fields inclusive – to choose from. We will select Retention Time to assess the trending of benzoic acid's Retention Time over six System Suitability standard injections.




Figure 9. Summary Plot Properties allow users to set the parameter that they would like to trend.

The Summary Line Plot of benzoic acid's Retention Time over six injections revealed that the injections were mostly trending near the lower error limit. Investigations and preventive corrective actions would be necessary to ensure that the method continues to maintain its optimum performance.




Figure 10. Summary line plot of benzoic acid's Retention Time trending over six injections.

Conclusion

Empower CDS allows for an assessment of your System Suitability standards in an automated manner. Laboratory productivity is increased as you do not have to manually assess System Suitability criteria. Upon failing the requirements, sample runs can be configured to continue, abort, or reinject the standards, allowing for a true hands-off system operation. Control charts provide you graphical representations of the result performance trends over time, allowing you to easily review and identify out-oftrend results.

Empower CDS's interactive System Suitability and control charts work in tandem to help assure that your laboratory continuously generates valid results while maintaining laboratory productivity.

Featured Products

Empower Chromatography Data System (CDS) <

https://www.waters.com/nextgen/global/products/informatics-and-software/chromatography-software/empower-software-solutions/empower-cds.html>

720007010, October 2020



© 2024 Waters Corporation. All Rights Reserved.

利用規約 プライバシーポリシー 商標 キャリア 法的通知およびプライバシー通知 Cookies Cookie 環境設定